

From: webmaster@cpuc.ca.gov <webmaster@cpuc.ca.gov>

Sent: Sunday, May 2, 2021 11:53 PM

To: usrb@cpuc.ca.gov

Cc: Paul Pimentel <Paul.Pimentel@sce.com>

Subject: (External):Electric Safety Incident Reported- Southern California Edison Company Incident No: 210502-14844

***** EXTERNAL EMAIL - Use caution when opening links or attachments *****

The Following information regarding this incident has been reported:

Reporting Date: 5/2/2021 11:50:36 PM

Incident Date: 5/2/2021 @ 7:55 p.m.

Reported By: Paul C. Pimentel, Senior Manager

Utility Name: Southern California Edison Company

Phone Number: (626)695-4705

Email Address: paul.pimentel@sce.com

Incident Location: Near 210th Street West and West Avenue D Lancaster, Los Angeles County

Reasons For Reporting:

- Fatalities? No (Utility: , Others:)
- Names of Fatalities:
- Injuries? (Utility: , Others:)
- Names of Injured:
- Damage? No (Utility: , Others:)
- Interruption? (Total Customers: , Total Hours:)
- Operator Judgement? Yes
- Media Coverage? Yes

Cause of Incident: Unknown (Other Cause:)

Agencies on Scene:

Facilities Affected:

- Utilities Facilities: Bailey-Neenach-Westpac
- Voltage (KV): 66 kV
- Customer's Facilities:

DigIn Information:

- Excavator Name:
- Contact:
- Phone: (____)____-____

Incident Recovery:

- On Scene Date & Time: @ 00:00 a.m.
- Service Restored: @ 00:00 a.m.

Summary: SCE submits this report out of an abundance of caution as it involves an event that may meet the subject of significant public attention or media coverage reporting requirement. Preliminary information reflects a brush fire known as the Delta Fire was reported west of Lancaster in Los Angeles County just before 8:00 p.m. The cause of the fire is under investigation and it has consumed approximately 100 acres of grass and brush. We have no reports of any injuries nor property damage attributed to the fire. Our information reflects circuit activity occurred prior to the report time of the fire. Additionally, a witness reported observing what was described as arcing power lines in the area where the fire was first reported. However, there are no reports of any downed conductors in the subject area and our investigation is ongoing.