

Fairview Fire ESIR: Additional Information¹

On September 5, 2022, SCE submitted an Electric Safety Incident Report (ESIR) to the California Public Utilities Commission (CPUC). SCE is required to submit a report to the CPUC on certain types of incidents that may involve utility facilities. The submission of the ESIR to the CPUC is intended to make the CPUC aware of an incident so that it can conduct its own investigation. In submitting the report, SCE is not conceding that its equipment caused the wildfire or that it is at fault for the damages caused by the wildfire. The cause of the fire is under investigation. The following information is solely with respect to the circuit referenced in the ESIR:

1. ESIR Reporting Date	9/5/2022
2. Circuit Located in High Fire Risk Area	Partial
3. PSPS Under Consideration on Circuit	No
4. Covered Conductor Installed on Circuit²	Partial
5. Circuit Length (miles)³	41.1
6. Fire Agency Information Link	LINK
7. ESIR Link	LINK

1. Information as of September 5, 2022. Data not subject to update
2. May not reflect in-flight work. In cases where the circuit is partially covered, SCE does not know whether circuit activity occurred on the covered or uncovered part of the circuit
3. Miles of overhead primary conductor