

Information Guide For the EEI SO/PD II (System Operator/Power Dispatcher) Test Battery

Test Number: 5209

Human Resources
Talent Planning and Programs
Southern California Edison
An Edison International Company

REV120115

Introduction

The **5209 EEI SO/PD II Test** is composed of four tests, designed and validated to aid in the selection of candidates for electrical utility system operator or power dispatching positions. This test was validated for positions including: System Operator, Substation Operator, Operator Trainee, Dispatcher Clerk, and Dispatcher Specialist.

Test Session

It is important that you follow the directions of the Test Administrator exactly. If you have any questions about the testing session, be sure to ask the Test Administrator before the testing begins. During testing, you may **NOT** leave the room, talk, smoke, eat, or drink. Since some tests take several hours, you should consider these factors before the test begins.

All cellular/mobile phones, pagers or other electronic equipment will <u>NOT</u> be allowed in the testing area.

The questions on three tests are multiple choice. One test is a multitasking simulation.

The test will take approximately two hours. No study aids are allowed on the test.

Information Guide Feedback

At the end of this Guide you have been provided with an Information Guide Feedback page. If a procedure or policy has changed, making any part of this Guide incorrect, your feedback would be appreciated so that corrections can be made.

SO/PD II STUDY MATERIALS STEP-BY-STEP INSTRUCTIONS

To help you prepare for this test, Edison Electric Institute, the test developer, has prepared an informational brochure and detailed practice tests. We recommend that you read through all practice tests and the brochure. The materials are online, and are accessible from any computer with internet access. From the websites you may read or print the materials.

*NOTE: Pop-up blockers may not allow the website to run correctly. If you use Pop-up blockers, it is recommended that they be turned off prior to accessing the site.

- 1. From any computer with internet access, type http://www.eei.org/practicetests in the address bar to access the practice tests, or http://www.eei.org/testingbrochures to access the test brochure. Type the above address(es) exactly as written.
- Both sites require the same username and password, assigned to Southern California Edison. To log in to the sites, enter the following information (case sensitive).
 Name: paper

Password: pen

Example:



3. Click on "System Operator/Power Dispatching II" (found on the left hand side of the webpage). From there you will be able to access the specific practice test modules or test brochure. You may print the documents if you wish.

Example:



Brochures

INTRODUCTION

Industry Testing Implementation Program

CADI

Career Assessment

CAST

Construction and Skilled Trades

CSR

Customer Service Representative

MASS

Power Plant Maintenance

MRAB

Meter Reader Aptitude Battery

POSS

Plant Operator

SASS

Support and Administrative (Computer)

SASS

Support and Administrative (Paper)

SO/PD II

System Operator/Power Dispatching II

TECH

Technician Occupations

Industry Testing Implementation Program (ITIP)

The EEI cooperative test validation studies are unprecedented in member company premises by member company personnel.

ITIP was created to protect the ongoing use of the validated tests, er

- 1. An intensive training and certification program for testing pers
- Development of a model testing policy for company use. Th requires: compliance with Federal and state regulations on er

EEI facilitates continuing quality assurance with professional and leg

Every effort has been taken to ensure that each test meets all Fe protected classes.

Copyright Statement

The set of electronically linked documents that you are currently viewing or reall such material located at or available on this Internet site, however referred any part of an original work prepared by a United States federal or state gover reproduced, downloaded, disseminated, published, or transferred, in any form of EEI and, pursuant to the appropriate Terms and Conditions of Use and/or I part of such content may be otherwise or subsequently reproduced, downloaded.



Troubleshooting Guide to Frequently Experienced Problems

- ➤ Pop-up blockers may interfere with your ability to access the study materials and practice tests. If you have pop-up blocker software installed, you may need to temporarily disable it. Contact your Internet Service Provider (America Online AOL, Earthlink, MSN, Verizon Online, etc).
- Anti-virus software (Norton Antivirus, Symantec, etc) may interfere with your ability to access the materials. If you are experiencing problems, you may want to consider temporarily adjusting the settings on your anti-virus software.
- ➤ If you experience an error message, such as "Internal Server Error," simply close your browser window, wait a few minutes, and try again.
- ➤ If you are still having problems, please call EEI at the help number listed on the website.

Info Guide Feedback

Please use this page to notify us of any changes in policies, procedures, or materials affecting this guide. Once completed, return to:

Southern California Edison Human Resources – Talent Planning & Programs G.O. 5 1st Floor 1515 Walnut Grove Ave. Rosemead, CA 91770

Test Name:	5209 EEI SO/PD II (System Operator/Power Dispatching) Test Battery
Page	Comments
	_
	_
	_